

Sale Name: Flashy Friday-UX

LOT UX11811 - Frigidaire 26 Cu. Ft. 36" Standard-Depth Side-by-Side Refrigerator | Damaged | (See Condition Notes)



Description

Frigidaire 26 Cu. Ft. 36" Standard-Depth Side-by-Side Refrigerator | Damaged | (See Condition Notes)

Condition Notes: Model: FRSS2623ASJ. Wall plug pins were bent. Refrigerator is giving "Power Outage" & "High Temp" warnings.

Condition: Damaged

<https://www.riograndeauctions.com/frequently-asked-questions#conditions>

Heavy: Yes

Oversized: Yes

Condición: Damaged

<https://www.riograndeauctions.com/preguntas#condition>

Pesado: Sí

Grande: Sí

Internal ID: CL2xELL-5326

Quantity: 1



— RIO GRANDE —
AUCTIONS
EL PASO, TEXAS

<https://www.riograndeauctions.com/>